East Shore Trail

Del Valle Regional Park

Trail Length 1.1 mi (1.8 km)

Network trail

This trail borders the east side of the lake. It is wide with some very steep grades. The trail passes campsites, picnic tables, and toilets. It offers beautiful views of the lake and surrounding hills, and sometimes a glimpse of a bald eagle or a heron.

Cumulative Elevation Change	**Gain 111 ft (34 m)** **Loss 96 ft (29 m)**

Typical Grade is 3.6%

12% of the trail is between 8% and 14%
79 ft (24 m) is between 12% and 14%
8% grade is a standard ramp.

Typical Cross Slope is 3.1%

21% of the trail is between 5% and 20%
162 ft (49 m) is between 10% and 20%

Typical Tread Width is 128 in (324 cm)

Tread Width ranges from 102 in (259 cm) to 280 in (711 cm)
Minimum Clearance 64 in (163 cm)

Trail Surface is Aggregate/Gravel

94% of the trail is Firm or better
325 ft (99 m) of the trail is Soft or worse

Trailhead Location

Dell Valle park is at the end of Del Valle Road off of Mines Road south of Livermore. The East Shore trail begins at the boat launch parking lot.

Trail Uses

- **Hiking**
- **Bicycling**
- **Equestrian**
- **No Motorized Vehicles**
- **Dogs**

Hazards and Obstructions

- **Ruts 5 in.**
- **Rocks 5 in.**

Trail Access Information

Warning: Trail conditions may have changed since this trail was assessed. Temporary obstructions (e.g. fallen trees or landslides) may not have been mapped. Maximum grades and cross slopes may vary.

Obstructions less than 2.0 in (5.0 cm) or outside the tread area wide by 96 in (2.4 m) high were not measured. Minimum clearance boundaries were at least high.

This report has been generated by TrailWare which has been created by Beneficial Designs, Inc.

Aug 26, 05

East Shore Trail

Length 1.1 mi (1.8 km)

Network trail

Hiking

Bicycling

Equestrian

Typical Grade 3.6%

12% of the trail is 8% to 14%

79 ft (24 m) is 12% to 14%

8% grade is a standard ramp.

Typical Cross Slope 3.1%

21% of the trail is 5% to 20%

162 ft (49 m) is 10% to 20%

Typical Tread Width 128 in (324 cm)

Minimum 102 in (259 cm)

Maximum 280 in (711 cm)

Minimum Clearance 64 in (163 cm)

Aggregate/Gravel

94% is Firm or better

325 ft (99 m) is Soft or worse

Ruts 5 in.

Rocks 5 in.

Trail Access Information

Warning: Trail conditions may have changed since this trail was assessed. Temporary obstructions (e.g. fallen trees or landslides) may not have been mapped. Maximum grades and cross slopes may vary.

This report is generated by TrailWare which has been created by Beneficial Designs, Inc.

Aug 26, 05

East Shore Trail

Del Valle Regional Park

Trail Access Information Summary

First Segment Assessed Jul 6, 05

Last Segment Assessed Jul 6, 05

Trail Length 1.1 mi (1.8 km)

Network trail

Cumulative Elevation Change

Gain 111 ft (34 m)

Loss 96 ft (29 m)

Typical Grade is 3.6%

12% of the trail is between 8% and 14%

79 ft (24 m) is between 12% and 14%

8% grade is a standard ramp.

Locations and lengths can be found on the Maximum Grade Table Reports

Typical Cross Slope is 3.1%

21% of the trail is between 5% and 20%

162 ft (49 m) is between 10% and 20%

Locations and lengths can be found on the Maximum X-Slope Table Reports

Typical Tread Width is 128 in (324 cm)

Tread Width ranges from 102 in (259 cm) to 280 in (711 cm)

Minimum Clearance Width is 64 in (163 cm)

Locations and lengths can be found on the Minimum Tread Width Table and Minimum Clearance Width Reports

Trail Surface is Aggregate/Gravel

94% of the trail is Firm or better

325 ft (99 m) of the trail is Soft or worse

Length of trail can be found on the Surface Type Table and Surface Category Table Reports.

Obstructions

Ruts 5 in.

Rocks 5 in.

Locations and lengths can be found on the Minimum Vertical and Maximum Tread Obstructions Reports

Trail Uses

Hiking

Bicycling

Equestrian

Warning: Trail conditions may have changed since this trail was assessed. Temporary obstructions (e.g. fallen trees or landslides) may not have been mapped. Maximum grades and cross slopes may vary. Obstructions less than 2.0 in (5.0 cm) or outside of the tread area wide by 96 in (2.4 m) high were not measured. Minimum clearance boundaries were at least high.